

GPSW050 Incoming AC Test

The incoming AC power should be between 108 to 130 VAC. Be sure to check the voltage with the motor on the operator running. Check to ensure there are not large fluctuations in the power within that range.

